

# MARION COUNTY SURVEYOR'S OFFICE



## SECTION CORNER RECORD

DEBRA S. JENKINS  
MARION COUNTY SURVEYOR

SEC. 22 TWN. 15<sub>N</sub> RNG. 3<sub>E</sub>

BRYAN F. CATLIN, PLS  
TECHNICAL SUPERVISOR

Date: 10-12-09  
Party Chief: Wilcoxen  
Crew: Finney  
Type of Marker: MCSO capped rebar  
Method of Establishment: County:  
IN S.P.C. E Zone, NAD 83  
Name: 15032204  
N: 497 565.514 1(m)  
E: 54 577.189 0(m)  
Survey Marker sign post installed



Corner originally set as a post in 1820 by Wm. B. Laughlin with the following witnesses: 2" cottonwood bearing N 24 E 43 links; and a 6" sycamore bearing N 71 W 31 links (Marion County Atlas p. 6). A survey by D.B. Hasbrook on 9/30/1852 indicates no stone but the following witnesses: 14" cottonwood bearing N 24 E 13 links; and a 16" cottonwood bearing S 10 W 11 links (Wayne Legal Book p. 52). Corner referenced by Wilcoxen on 2/16/2000 and called a MCSO capped rebar. Corner referenced by Wilcoxen on 10/12/09 and called a MCSO capped rebar with a sign post by it.

REF.	DISTANCE	DESCRIPTION
1.	9.34'	Mag nail w/brass washer W 4" locust 36" up
2.	6.58'	Mag nail w/brass washer NE 4" locust 24" up
3.	12.15'	Mag nail NE 4" locust 24" up
4.	2.48'	Threaded bolt top of 3" pipe
5.	13.62'	Mag nail w/brass washer W 4" scrub 15" up

--